



Do you “twist push” your connections ?

Accidental anaesthesia breathing tube disconnections can lead to COVID viruses leaking out.



Breathing tube connectors typically are “tapered” and have slightly slanted surfaces. When making a connection in such a system, twist the connectors while you push them together. The twisting action makes the connection much stronger than if you just pushed them together without twisting.



“twist while pushing”

“Twist Push” your connections for safety !